

✓

Annexure D

BUILDING SAFETY CERTIFICATE

No. 535

Dated: 5/05/2025

It is certified that the existing building HVPS International School at Oshiwara Tal. Andheri, Dist. Mumbai Suburban is having block (s) Floor (s) as per details below :

| Detail of Block(s) in school | Block (1) | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|------------------------------|-------------------------------------|-----------|-----------|-----------|-----------|-----------|
| No. of Floor(s) in the Block | Ground +9 th upper Floor | - | - | - | - | - |

The building is owned/occupied by HVPS International School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PUBLIC WORK DEPARTMENT (Name of Department/ Govt.) on 23/04/2025 (date of inspection) in the presence of Mr. Santosh Nirmal –Manager- Oshiwara Tal. Andheri, Dist. Mumbai Suburban and that building /premises is fit for occupancy for running school with effect from 23/04/2025 for a period of 3 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1
- 2.
- 3.
- 4.

Issued on 5/05/2025 at P.W.D. by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal



Name & Address of Department/ Office:

EXECUTIVE ENGINEER
NORTH MUMBAI (P.W.) DIVISION
ANDHERI, MUMBAI-400 058

For HVPS International School

Seerif Haider
Principal